

1. Approving Civil Aviation Authority/Country: **FAA/UNITED STATES**

2. **AUTHORIZED RELEASE CERTIFICATE**
FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number: **220263**

4. Organization Name and Address: **Galaxy International, Inc.**
1658 S. LITCHFIELD ROAD
HANGAR 18
GOODYEAR, AZ 85338
USA
Ph: 623-882-2783, Fax: 623-882-2790
FAA Approval Holder: GOXR924Y

5. Work Order/Contract/Invoice Number: **R10124**

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	LUBE PUMP	3881000-7	1.00	1214	INSPECTED

12. Remarks:
 INSPECTED REFERENCING Manual ID: 49-91-49, Revision #: 9, Revision Date: 1/9/2019

FULL DETAILS HELD ON WO: 220263

Certifies work specified in Blocks 11/12 was carried out in accordance with EASA Part 145, and with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA.145.5645.

13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12		14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13b. Authorized Signature:	13c. Approval Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
_____	_____	_____	_____
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mm/yyyy):
_____	_____	_____	_____

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Galaxy International, Inc.
1658 S. LITCHFIELD ROAD
HANGAR 18
GOODYEAR, AZ 85338
USA
Ph: 623-882-2783, Fax: 623-882-2790

Tear Down/Inspection

Work Order #: 220263

Date Printed: 7/14/2022

Time: 8:20:54 AM

Page: 1

To:
ATTN: SALES
SALT RIVER AVIATION
2675 E CESSNA DRIVE #102
CHANDLER, AZ 85286
UNITED STATES OF AMERICA

Ship To:
SALT RIVER AVIATION
2675 E CESSNA DRIVE #102
CHANDLER, AZ 85286
UNITED STATES OF AMERICA

FORM GI-Q-121B

Ref #: R10124

Phone #: 480-558-1455

Fax #: 480-558-1456

Email: ellen@saltriveraviation.com

Code: SRA

Site:

PN: 3881000-7

Descr: LUBE PUMP

Qty: 1

Station:

Make:

Model:

Mfg: _

Serial Numbers: 1214

Symptoms:

INCOMING NOTES

VERIFIED PN AND SN
OBTAINED INSPECTION PHOTOS
UNIT APPEARS INTACT

REASON FOR REMOVAL

NOT PROVIDED

WORK REQUESTED

PLEASE INSPECT IAW CURRENT REVISION OF THE OEM MANUAL
ENSURE UNIT IS PART MARKED CORRECTLY

CERT REQUESTED

RELEASE WITH DUAL 8130/EASA

PRELIM INSPECTION/TEST

UNIT INSPECTED

Faults:

TEARDOWN FINDINGS:

INSPECTED FILTERS AND NO METAL CONTAMINATION FOUND
INSTALLED SAFETY WIRE ON ONE OF THE SWITCHES

Corrective Actions:

INSPECT

INSPECTED UNIT REFERENCING
49-91-49, REVISION 9, DATED JANUARY 9, 2019



Galaxy International, Inc.
 1658 S. LITCHFIELD ROAD
 HANGAR 18
 GOODYEAR, AZ 85338
 USA
 Ph: 623-882-2783, Fax: 623-882-2790
 sales@galaxyinternational.com

Packing Slip

Invoice #: 220263
 Invoice Date: 7/14/2022
 Time: 8:29:18 AM
 Page: 1

To:
 SALT RIVER AVIATION
 2675 E CESSNA DRIVE #102
 CHANDLER, AZ 85286
 UNITED STATES OF AMERICA
 ATTN: SALES

Ship To:
 SALT RIVER AVIATION
 2675 E CESSNA DRIVE #102
 CHANDLER, AZ 85286
 UNITED STATES OF AMERICA

Cust. PO#: R10124	Terms: NET 30	Ship Via: FEDEX GROUND	Ship Via Acc: 342809367
Order Date: 0	# of Items: 1	# of Boxes:	Weight:
Prepared By:	Sales Order:	Ship Log #: 0	Ship Order:
Customer #: SRA	FOB:	Cust VAT #:	Ship Date: 7/14/2022
Buyer: SALES	Req. Ref#:	VAT #:	Shipment:
		WO #: 220263	AWB: 777386603640

Item	Part Number/Description	Shipped	BackOrd	CD			Unit Price	UOM	Total Amt
1	3881000-7 LUBE PUMP Control #: 0-0	1.00	0.00						

Special Instructions: